



- 35.901.16
- 35.901.16 10
- 35.901.16 12
- 35.901.16 18
- 35.901.16 20
- 35.901.16 23
- 35.901.16 40

- 61.1802.47 Ø1.5 - 35.901.16
- 61.1802.45 Ø1.0 - 35.901.16 10
- 61.1802.46 Ø1.2 - 35.901.16 12
- 61.1802.48 Ø1.8 - 35.901.16 18
- 61.1802.55 Ø2.0 - 35.901.16 20
- 61.1802.68 Ø2.3 - 35.901.16 23
- 35.1802.56 Ø4.0 - 35.901.16 40

Come si ordina/How to order
 Kit riparazione-Cod. **35.302.18**
 Repair kit-C/N.

| | | | |
|---|-----------------------|-----|------------------------------------|
| Percorso file 3D: U:/Archivio/braglia/Esplosi/35.901.16.pkg | | | |
| DENOMINAZIONE: Lancia Spot | | | N°revisione 02 |
| | | | Data revisione: 23/12/09 |
| Braglia SRL I-42029 Masone (REGGIO EMILIA)-ITALY-UE | Tel. ++39 0522 340648 | STE | RTE |
| | Fax. ++39 0522 345025 | | |
| Email: braglia@braglia.it | | | Dis.N°/Codice 35.901.16 |